From: NAVFAC MIDLANT, ROICC Camp Lejeune

NAVFAC MIDLANT, Staff; (b)(6) NAVFAC MIDLANT, BD To: NAVFAC MIDLANT, ROICC Camp Lejeune; (6) NAVFAC MIDLANT, ROICC Camp Lejeune

Correspondence Regarding Group III (Email 6), Freedom of Information Act (FOIA) Request DON-NAVY-2017-Subject:

003161 - Camp Lejeune - P1383 & P1384 Base Entry Point / CLEO Building Projects Contract No. K1310-002-S /

Project Number K1310 SLO Case No. 16-970

Date: Friday, May 12, 2017 13:27:57

Non-DoD Source TRANSMITTAL 1262 SPEC 27 10 00 TELECOMMUNICATIONS CABLING SYSTEM SD-03 Attachments:

OUTDOOR RATED CAT-6 CABLE.msg

Non-DoD Source FW INDOOROUTDOOR CAT-6 CABLE.msg

RE CAMP LEJEUNE WILSON GATE VISITOR"S CENTER - ACOUSTICAL WALL TREATMENT .msg

Non-Dod Source FW CAMP LEJEUNE WILSON GATE VISITOR"S CENTER - ACOUSTICAL WALL TREATMENT .msg RE Transmittal 1217 REV1 SPEC 23 08 00.00 10 COMMISSIONING OF HVAC SYSTEMS SD-02 AND SD-03.msg

RE P-1383 Non-DoD Source Re PRELIMINARY CLEO TAB REPORT.msg

Non-DoD Source FW Transmittal 1217 REV1 SPEC 23 08 00.00 10 COMMISSIONING OF HVAC SYSTEMS SD-02

AND SD-03.msg


RE P-1383 Non-DoD Source Re PRELIMINARY CLEO TAB REPORT.msg

Non-Dod Source RE CAMP LEJEUNE WILSON GATE VISITOR"S CENTER - ACOUSTICAL WALL TREATMENT .msg

RE CAMP LEJEUNE WILSON GATE VISITOR"S CENTER - ACOUSTICAL WALL TREATMENT .msg

RE P-1383 Non-Dod Source Re PRELIMINARY CLEO TAB REPORT.msg
Non-Dod Source CAMP LEJEUNE WILSON GATE VISITOR"S CENTER - ACOUSTICAL WALL TREATMENT .msg Non-Dod Source CAMP LEJEUNE WILSON GATE VISITOR"S CENTER - ACOUSTICAL WALL TREATMENT .msg

FYI



From: (b)(6)

To: NAVFAC MIDLANT, CI (b)(6) NAVFAC MIDLANT, ROICC Camp Lejeune;

NAVFAC MIDLANT, CI (b)(6)

NAVFAC MIDLANT, ROICC Camp Lejeune (b)(6)

Cc: (b)(6) (PM, Group III Management); (b)(6)

(Group III Mgt Superintendent) (b) (6)

Subject: [Non-Dod Source] CAMP LEJEUNE WILSON GATE VISITOR"S CENTER - ACOUSTICAL WALL TREATMENT

Date: Thursday, May 19, 2016 16:59:00

Attachments: <u>image001.png</u>

Importance: High

Good afternoon (b)(6). The acoustic wall panel color that was submitted and approved in the submittal is no longer available. The fabric style you proposed was a Maharam fabric style and the color was TEK-WALL view 399432; 004 glacier. The manufacturer says this color is being phased out. They don't have any leftover stock. Maharam recommends the following as alternatives.

Tek-Wall 1002 001

Tek-Wall Annex 001, 002, 008

Tek-Wall Band 001

Tek-Wall Drift 004

Tek-Wall Lintel 003, 004

Tek-wall Measure Backed 003, 001

Tek-Wall Ramble 001

Tek-Wall Steward 001

Tek-Wall Tint 003, 002

Tek-Wall View 001, 003, 102

These can be viewed easily and clearly on their website at http://maharam.com/search?query=tek-Wall http://maharam.com/search?query=tek-Wall

Will you please review and select an alternate color? Thanks. R/

(b)(6) | Deputy Project Manager & Small Business Liaison | cid:image001.png@01CCA871.8C8E7960 |

311 Parachute Tower Road | Camp Lejeune, NC 28542 |

Dragados USA, Inc. is An Equal Opportunity Employer

From: To: NAVFAC MIDLANT, ROICC Camp Lejeune (b) NAVFAC MIDLANT, NAVFAC MIDLANT, ROICC Camp Lejeune; ROICC Camp Lejeune NAVFAC MIDLANT, CI Cc: (PM, Group III Management); (b) (6 Subject: [Non-DoD Source] FW: Transmittal 1217, REV1, SPEC 23 08 00.00 10, COMMISSIONING OF HVAC SYSTEMS, SD-02 AND SD-03 Date: Thursday, May 26, 2016 8:26:56 Attachments: image001.png These are not reasons for rejection of the submittal. Not sure if this is what you meant? If Good afternoon there is a system that is not in the project than the commissioning agent can mark "N/A". Alternatively reply "Concur with comment and his comment can be to strike the systems not on the project for the final report. Do you agree? Thanks. R.(b)(6) Good afternoon (b). I never saw a response from AMEC/CEMS. Thanks. R. | Deputy Project Manager & Small Business Liaison | cid:image001.png@01CCA871.8C8E7960 | 311 Parachute Tower Road | Camp Lejeune, NC 28542 | Phone: w | Email: <mailto Dragados USA, Inc. is An Equal Opportunity Employer ----Original Message----From: NAVFAC MIDLANT, ROICC Camp Lejeune [mailto raymond.conroy@navy.mil] Sent: Friday, May 20, 2016 6:32 AM NAVFAC MIDLANT, ROICC Camp Lejeune; To (b) NAVFAC MIDLANT, ROICC Camp Lejeune; (b)(6) (AMEC Programs):(b)(6 NAVFAC MIDLANT, CI (Group III Mgt.); (PM, Group III Management); (Group III Mgt Superintendent):(b)(6) Subject: RE: Transmittal 1217, REV1, SPEC 23 08 00.00 10, COMMISSIONING OF HVAC SYSTEMS, SD-02 AND SD-03

(b)

The only comments were from (b)(6) " Table 12.1 Group 3 top section appears to include systems not in the project (i.e.: Nat. Gas Boilers, etc.)".

We're trying to locate the hard copies so you have an official response, where/who were they sent to?

Engineering Technician ----Original Message----- $[\underline{\text{mailto}}(b)(6)]$ <mailto Sent: Wednesday, May 18, 2016 3:52 PM NAVFAC MIDLANT, ROICC Camp Lejeune; (b)(6) NAVFAC MIDLANT, NAVFAC MIDLANT, ROICC Camp Lejeune; ROICC Camp Lejeune: (AMEC Programs):(b)(6) <<u>mailto</u> <mailto NAVFAC MIDLANT, CI (Group III Mgt.);(b)(6) (PM, Group III Management):(b) Cc (b)(6) (Group III Mgt Superintendent); <mailto Subject: [Non-DoD Source] FW: Transmittal 1217, REV1, SPEC 23 08 00.00 10, COMMISSIONING OF HVAC SYSTEMS, SD-02 AND SD-03 Good afternoon. Is there a designer response to this re-submittal of the CLEO HVAC commissioning submittal? Thanks. R(b)(6) | Deputy Project Manager & Small Business Liaison | | 311 Parachute Tower Road | Camp Lejeune, NC 28542 | | Email: (b) (6 Phone: w (b) (6) <mailto Dragados USA, Inc. is An Equal Opportunity Employer

has been handling this and he is out for three weeks and I do not want to hold you up.

From: To: NAVFAC MIDLANT, ROICC Camp Lejeune (b) NAVFAC MIDLANT, NAVFAC MIDLANT, ROICC Camp Lejeune; ROICC Camp Lejeune NAVFAC MIDLANT, CI Cc: (PM, Group III Management);(b)(6 Subject: [Non-DoD Source] FW: Transmittal 1217, REV1, SPEC 23 08 00.00 10, COMMISSIONING OF HVAC SYSTEMS, SD-02 AND SD-03 Date: Thursday, May 26, 2016 8:26:56 Attachments: image001.png . These are not reasons for rejection of the submittal. Not sure if this is what you meant? If Good afternoon there is a system that is not in the project than the commissioning agent can mark "N/A". Alternatively, reply "Concur with comment and his comment can be to strike the systems not on the project for the final report. Do you agree? Thanks. R.(b)(6) . I never saw a response from AMEC/CEMS. Thanks. R. Good afternoon | Deputy Project Manager & Small Business Liaison | cid:image001.png@01CCA871.8C8E7960 | 311 Parachute Tower Road | Camp Lejeune, NC 28542 | Phone: w(b)(6) | Email: Dragados USA, Inc. is An Equal Opportunity Employer ----Original Message----From NAVFAC MIDLANT, ROICC Camp Lejeune [mailto (b) Sent: Friday, May 20, 2016 6:32 AM NAVFAC MIDLANT, ROICC Camp Lejeune; To NAVFAC MIDLANT, ROICC Camp Lejeune (b) (6) (AMEC Programs):(b)(6 NAVFAC MIDLANT, CI (PM, Group III Management); (Group III Mgt.); (Group III Mgt Superintendent):(b)(6) Subject: RE: Transmittal 1217, REV1, SPEC 23 08 00.00 10, COMMISSIONING OF HVAC SYSTEMS, SD-02

(b)(6)

AND SD-03

The only comments were from (b)(6) " Table 12.1 Group 3 top section appears to include systems not in the project (i.e.: Nat. Gas Boilers, etc.)".

We're trying to locate the hard copies so you have an official response, where/who were they sent to?

has been handling this and he is out for three weeks and I do not want to hold you up. **Engineering Technician** ----Original Message-----From: (b)(6) [<u>mailto:</u>(b)(6) <<u>mailto</u> Sent: Wednesday, May 18, 2016 3:52 PM NAVFAC MIDLANT, ROICC Camp Lejeune; (b)(6) NAVFAC MIDLANT, NAVFAC MIDLANT, ROICC Camp Lejeune; ROICC Camp Lejeune; (AMEC Programs); (b)(6) NAVFAC MIDLANT, CI (Group III Mgt.); (b)(6) (PM, Group III Management); (b) (Group III Mgt Superintendent); Subject: [Non-DoD Source] FW: Transmittal 1217, REV1, SPEC 23 08 00.00 10, COMMISSIONING OF HVAC SYSTEMS, SD-02 AND SD-03 Good afternoon. Is there a designer response to this re-submittal of the CLEO HVAC commissioning submittal? Thanks. R(b)(6) | Deputy Project Manager & Small Business Liaison | | 311 Parachute Tower Road | Camp Lejeune, NC 28542 | | Email: (b)(6 Phone: w (b) (6) <mailto Dragados USA, Inc. is An Equal Opportunity Employer


From: NAVFAC MIDLANT, ROICC Camp Lejeune (6) To: NAVFAC MIDLANT, ROICC Camp Lejeune (b) (6 Camp Lejeune; (b) (6) NAVFAC MIDLANT, ROICC Camp Lejeune (PM, Group III Management) Subject: [Non-DoD Source] TRANSMITTAL 1262, SPEC 27 10 00, TELECOMMUNICATIONS CABLING SYSTEM, SD-03, **OUTDOOR RATED CAT-6 CABLE** Date: Thursday, June 02, 2016 12:36:26 Attachments: image001.png 1262, SPEC 27 10 00, TELECOMMUNICATIONS CABLING SYSTEM, SD-03, OUTDOOR RATED CAT-**TRANSMITTAL** 6 CABLE.pdf Good morning (b)(6). Attached is product data for the outdoor-rated telecomm cable for the CLEO building. Steve Daigle has already stated this product is acceptable. Hard copies of this transmittal are enroute to your office. Thanks. R/ | Deputy Project Manager & Small Business Liaison | cid:image001.png@01CCA871.8C8E7960 | From: (b)(6) Sent: Thursday, June 02, 2016 10:25 AM (NAVFAC Contract Spec); (b) (6 (Dragados QC Specialist):(b)(6) (Dragados Senior Vice President); (b) (6) Cc: (b)(6) III Management) Subject: FW: INDOOR/OUTDOOR CAT-6 CABLE Good morning. Below is Base Telephone's approval of an outdoor-rated CAT-6 cable we intend on using at the CLEO building. My QC Manager will submit this product data sheet today but with (b)(6) prior approval of the material I am authorizing my sub to install it tomorrow (3Jun). Thanks. R/ | Deputy Project Manager & Small Business Liaison | | ----Original Message----From: [mailto Sent: Thursday, June 02, 2016 10:02 AM To:

The attached product data sheet is acceptable to Base Telephone for the conduit running through the slab at the CLEO building, but only the ROICC can approve.

Subject: RE: INDOOR/OUTDOOR CAT-6 CABLE

Cc:

I can only advise and recommend but have no approval authority, please contact the CM or ET for proper submittal procedures on the attached ...




From: NAVFAC MIDLANT, ROICC Camp Lejeune; (b) (6) To: CIV NAVFAC MIDLANT, ROICC Camp Lejeune (b) (6 Camp Lejeune (b) (6) NAVFAC MIDLANT, ROICC Camp Lejeune (PM, Group III Management) Subject: [Non-DoD Source] TRANSMITTAL 1262, SPEC 27 10 00, TELECOMMUNICATIONS CABLING SYSTEM, SD-03, **OUTDOOR RATED CAT-6 CABLE** Date: Thursday, June 02, 2016 12:36:26 Attachments: image001.png 1262, SPEC 27 10 00, TELECOMMUNICATIONS CABLING SYSTEM, SD-03, OUTDOOR RATED CAT-**TRANSMITTAL** 6 CABLE.pdf Good morning (b)(6). Attached is product data for the outdoor-rated telecomm cable for the CLEO building. Steve Daigle has already stated this product is acceptable. Hard copies of this transmittal are enroute to your office. Thanks. R. (b) (6) | Deputy Project Manager & Small Business Liaison | cid:image001.png@01CCA871.8C8E7960 | From: (b)(6) Sent: Thursday, June 02, 2016 10:25 AM (NAVFAC Contract Spec); (PM, Group Cc III Management) Subject: FW: INDOOR/OUTDOOR CAT-6 CABLE Good morning. Below is Base Telephone's approval of an outdoor-rated CAT-6 cable we intend on using at the CLEO building. My QC Manager will submit this product data sheet today but with (b)(6) prior approval of the material I am authorizing my sub to install it tomorrow (3Jun). Thanks. R. (b) (6) | Deputy Project Manager & Small Business Liaison | |

-----Original Message----From: (b)(6) [mailto(b)(6)]
Sent: Thursday, June 02, 2016 10:02 AM
To (b)(6)
Cc: (b)(6)
(b)(6)

Subject: RE: INDOOR/OUTDOOR CAT-6 CABLE

The attached product data sheet is acceptable to Base Telephone for the conduit running through the slab at the CLEO building, but only the ROICC can approve.

I can only advise and recommend but have no approval authority, please contact the CM or ET for proper submittal procedures on the attached ...



Dragados USA, Inc. is An Equal Opportunity Employer

CONT	RACTOR'S SUBMITT	AL TRANSMITTAL		CONTRACT NO.	TRANSMITT	AL NO.	DATE	
LANTE	IV NORFOLK 4-43553 (Rev. 11-80)		N40085-12-C-7714	06022016	1262	6/2/2016	
FROM	CONTRACTOR (b)(6)			PROJECT TITLE AND LO	CATION			
Draga	idos USA -							
(b)(6)		12/27-2		P1383 & P1384 - New Bas	se Entry Point	and Road at M	CB Camp Lejeune	
	Supervisory	Construction Mgr						
		CONTRACTOR U				REVIEWER USE ONLY		
		*List only one specification	division pe	er form		** ACTION CODES		
	Tiet only one	-64b - 6-11i		too-oittel forms		A-Approve		
	-	of the following categor				D-Disapproved AN-Approved as noted RA-Receipt acknowledged C-Comments		
		and indicate which is t	eing sub	milled				
_ ^-	atractas Approved	OICC Ap	provol	Deviation	/Substitution			
0	ntractor Approved	- OICC A	pprovar		CC Approval	R-Resubmit		
ITEM	PROJ. SPEC. SECT. & PARA. and/or		IDENTIFICA		NO. OF	ACTION CODES	REVIEWER'S INITIALS	
NO	PROJ. DWG. NO.	1 21 1	ochure numb	_	COPIES	***	CODE AND DATE	
1	27 10 00	Building Telecommun	nications	Cabling System	3			
111		VISITOR'S CENTE						
		SD-03 Product Da	ata - Tele					
				/outdoor CAT-6 cable:				
	para 2.3.1.	2	3AVVG, p	oolyethylene insulation			-	
_								
CONT	RACTOR'S COMMENTS							
This	material is for the un	der-slab conduit at the	CLEO si	ite. Thanks. R/				
				(h)(C)				
				(D)(O)				
*				CONTRACTO				
9		Tenan in						
DATE	RECEIVED BY REVIEWER	FROM (Review	ver)					
-				lana antitach de economical de	and day to the control	am the		
		ith action indicated. Approval less the contractor calls attent			my deviation fro	om trie		
	•	to LANTDIV with A-E recomme		• •	NLY Section an	d in comments		
	below on ONE COPY of th	e transmittal form.						
REVIE	WER'S COMMENTS							
COPIES	TO:		DATE		SIGNATURE			
	CC (2)				3.5			
LAN	TDIV (1)							
A-E	1)							



Comtran Cable LLC 330A Turner Street South Attleboro, MA 02703-7714 (P) 508-399-7004 (F) 508-399-7360 www.ComtranCorp.com

Design Specification 35952

Category 6 Indoor/Outdoor LSZH CM-LS

Construction:

* Conductors: 23 AWG Solid Bare Copper per ASTM B-3

* Insulation: Polyethylene

* Pair Assembly: Color Coded Conductors Twisted to Varying Lays

* Cable Assembly: 4 Pairs Cabled With a LSZH X-Web

* Flooding Compound

* Jacket:

Black LSZH

Nominal OD = .290"

Features:

- * Prevents Against Moisture Migration
- * Superior 4 pair Balance for Increased Margins
- * Exceeds the Limited 50 ft. Entrance of Standard OSP Cables
- * Excellent Cross Talk characteristics

Compliance:

- * ETL Verified ANSI/TIA-568-C.2 Cat 6
- * UL Subject 444 Communications Cables
- * UL Listed type CM-LS
- * Sunlight Resistant Per UL 2556
- * NEC Article 800
- * ICEA S-90-661
- * California State Fire Marshal
- * RoHS Compliant
- * Voltage Rating 300

Common Applications:

- * Gigabit Ethernet (1000Base-T)
- * Multimedia & ISDN
- * High Speed Voice/Data applications
- * 1.2 Gbps Ethernet
- * Broadband Video

Category 6 Electricals

Return **PSNEXT** ACRF **PSACRF** Char. Impedance Attenuation NEXT Loss (dB/100m) (dB/100m) (dB/100m) (dB/100m) (dB/100m) (Ohms) (dB) Freq (Min) (Min) (Min) (Min) (Max) (Min) (MHz.) (+/-15)72.3 64.8 100 20 2 74.3 67.8 1 52.8 63.3 65.3 55.8 3.8 4 100 23 46.7 58.8 49.7 100 24.5 5.3 60.8 8 44.8 57.3 47.8 59.3 10 100 25 6 54.2 40.7 43.7 16 100 25 7.6 56.2 52.8 38.8 41.8 20 100 25 8.5 54.8 51.3 36.8 39.8 25 100 24.3 9.5 53.3 34.9 49.9 31.25 100 23.6 10:7 51:9 37.9 28.9 45.4 31:9 62.5 100 21-5 15.4 47.4 42.3 24.8 44.3 27.8 20.1 19.8 100 100 22.8 40.9 100 19.4 22.4 42.9 25.8 125 20.9 39.4 25.2 41.4 23.9 155 100 18.8 19.9 38.7 26.9 40:7 22.9 175 100 18.4 37.8 18.8 29 39.8 21-8 200 100 18 36.3 19.8 16.8 38.3 17.3 32.8 100

Print: COMTRAN CABLE LLC COM-LINK INDOOR/OUTDOOR CAT 6 250 MHZ 23 AWG CM-LS C(UL)US SUNLIGHT RESISTANT ETL VERIFIED TO ANSI/TIA-568-C.2 CATEGORY 6 ROHS (01-12345) 000002

DRAWING	REV	DATE	Drwn.	App.	REMARKS	35952
35952	01	8/6/14	BAL	JВ	Initial Release	Page 1 of 1

To: NAVFAC MIDLANT, CI (b) (6) NAVFAC MIDLANT, ROICC Camp Lejeune [Non-Dod Source] RE: CAMP LEJEUNE WILSON GATE VISITOR"S CENTER - ACOUSTICAL WALL TREATMENT Subject: Date: Wednesday, May 25, 2016 15:12:06 [b] I'll let you know ASAP. Thanks. R/ | Deputy Project Manager & Small Business Liaison | | 311 Parachute Tower Road | Camp Lejeune, NC 28542 | Email:(b)(6) Dragados USA, Inc. is An Equal Opportunity Employer **** Confidential ***** This electronic message transmission contains information from Dragados USA Inc., that may be confidential or privileged. The information is intended to be for the use of only the individual or entity named above and not to be distributed to other companies or individuals. If you are not the intended recipient, be aware that any disclosure, copying, distribution or use of the contents of this information is strictly prohibited. If you have received this electronic transmission in error, please notify the sender by reply e-mail immediately and delete this e-mail and any attachments from your system and any copies you may have made, electronic or otherwise. ----Original Message----From: (b) NAVFAC MIDLANT, CI [mailto(b)(6) Sent: Wednesday, May 25, 2016 1:50 PM NAVFAC MIDLANT, ROICC Camp Lejeune; NAVFAC MIDLANT, ROICC Camp Lejeune; (b)(6) (PM, Group III Management);(b)(6) (Group III Mgt Superintendent); (b)(6) Subject: RE: CAMP LEJEUNE WILSON GATE VISITOR'S CENTER - ACOUSTICAL WALL TREATMENT Are any of the following available? Tek-wall Parable 398650 #006 Value Tek-wall Subject 399535 #003 Snowcap Tek Wall Sum 399592 #003 Blizzard Any of those three would be acceptable. V/r, CID NAVFAC Mid-Atlantic Capital Improvements, CI4B Interior Designer Office (b) (6) ----Original Message----From [mailto(b) Sent: Thursday, May 19, 2016 5:10 PM NAVFAC MIDLANT, CI:(b)(6) NAVFAC MIDLANT, ROICC Camp Lejeune: (b) (6) NAVFAC MIDLANT, ROICC Camp Lejeune; (PM, Group III Management); (b)(6)

From:

(Group III Mgt Superintendent); (b)(6)

Subject: [Non-DoD Source] CAMP LEJEUNE WILSON GATE VISITOR'S CENTER - ACOUSTICAL WALL

TREATMENT Importance: High

RE-SENDING: I forgot to include supporting information. Thanks. R/

Good afternoon (b)(6). The acoustic wall panel color that was submitted and approved in the submittal is no longer available. The fabric style you proposed was a Maharam fabric style and the color was TEK-WALL view 399432; 004 glacier. The manufacturer says this color is being phased out. They don't have any leftover stock. Maharam recommends the following as alternatives.

Tek-Wall 1002 001

Tek-Wall Annex 001, 002, 008

Tek-Wall Band 001

Tek-Wall Drift 004

Tek-Wall Lintel 003, 004

Tek-wall Measure Backed 003, 001

Tek-Wall Ramble 001

Tek-Wall Steward 001

Tek-Wall Tint 003, 002

Tek-Wall View 001, 003, 102

These can be viewed easily and clearly on their website at http://maharam.com/search?query=tek-Wall http://maharam.com/search?query=tek-Wall

Will you please review and select an alternate color? Thanks. R/(b)

(b)(6) | Deputy Project Manager & Small Business Liaison | cid:image001.png@01CCA871.8C8E7960 |

311 Parachute Tower Road | Camp Lejeune, NC 28542 |

Phone: w(b)(6) | c(b)(6) | Email:(b)(6) | cmailto(b)(6) | >

Dragados USA, Inc. is An Equal Opportunity Employer

From: (b)(6)
To: (b)(6)

NAVFAC MIDLANT, CI; (b) (6) NAVFAC MIDLANT, ROICC Camp Lejeune;

NAVFAC MIDLANT, ROICC Camp Lejeune (b) (6)

Cc: (b)(6)

(PM, Group III Management) (b) (6)

(Group III Mgt Superintendent); (b

Subject: [Non-Dod Source] CAMP LEJEUNE WILSON GATE VISITOR"S CENTER - ACOUSTICAL WALL TREATMENT

Date: Thursday, May 19, 2016 17:11:09

Attachments: image001.png

ACOUSTIC PANEL BACKUP INFO.pdf

Importance: High

RE-SENDING: I forgot to include supporting information. Thanks. R/

Good afternoon (b)(6). The acoustic wall panel color that was submitted and approved in the submittal is no longer available. The fabric style you proposed was a Maharam fabric style and the color was TEK-WALL view 399432; 004 glacier. The manufacturer says this color is being phased out. They don't have any leftover stock. Maharam recommends the following as alternatives.

Tek-Wall 1002 001

Tek-Wall Annex 001, 002, 008

Tek-Wall Band 001

Tek-Wall Drift 004

Tek-Wall Lintel 003, 004

Tek-wall Measure Backed 003, 001

Tek-Wall Ramble 001

Tek-Wall Steward 001

Tek-Wall Tint 003, 002

Tek-Wall View 001, 003, 102


These can be viewed easily and clearly on their website at http://maharam.com/search?query=tek-Wall http://maharam.com/search?query=tek-Wall


Will you please review and select an alternate color? Thanks. R/(b)


Phone: w (b)(6) | c(b)(6) | Email: (b)(6) | Email: (b)(6) | |

Dragados USA, Inc. is An Equal Opportunity Employer

V NORFOLK 4-4355	TTAL TRANSMITTAL	CONTRACT NO.	TRANSMITTA	AL NO.	DATE		
		N40085-12-C-7714	06252014	808	6/25/2014		
CONTRACTOR (b)(6)		PROJECT TITLE AND LOC	PROJECT TITLE AND LOCATION				
dos USA -		P1383 & P1384 - New Base	Entry Point and f	Road at MCE	3 Camp Lejeune		
USN	I, CEC						
			-		EWER USE ONLY		
	*List only one specification divis	ion per form			ACTION CODES		
List only or	ne of the following categories	on each transmittal form.		D-Disapproved AN-Approved as noted			
	and indicate which is being	g submitted	1				
	C 0100 A	Devilati	and Cubatilities		elpt acknowledged		
ractor Approved	☐ Olde Approval		66 68	R-Result			
PROJ. SPEC. SECT.		IFICATION	NO. OF	ACTION	REVIEWER'S INITIALS		
PROJ. DWG. NO.			COPIES	CODES	CODE AND DATE		
00.03.13	Acquetical Mail Treatment			Δ	A/W/14 KX		
					710711		
				A	19/11/11 AC		
para 2.1		onnond ACT occuption	+	_/\	110/19 750		
	panels	espond ACT acoustical					
				,	1		
0 4 4				A	9/10/14 AGAK		
para 2.1.A.	submitting to x to in this st	iomittai.			+		
				٨	alain Act		
Para 2.1.D.	polyester.	post-consumer recycled		A	MIDITIA HOP		
	Color: Sample provided,	Maharam, matches		٨	9/10/14 ASK		
para 2.2	room finish schedule, pla	n sheet A-602		7	אוטוע אסר		
para 1.2	SD-04, Product samples			A	1/10/14 AS		
para 1.2.	SD-07, Certificates						
ACTOR'S COMMEN	rs						
s. R/							
					ji		
		CONTRACTOR REPRESENTA	TIVE (Signature)				
			4911		24		
CEIVED BY REVIEWER	FROM (Reviewer)		то				
Submittale are returned	with action indicated. Approve of an	item does not include approval of	enu deviation from	, the			
			arry deviation from	1 1110			
		ons Indicated in REVIEWER USE O	NLY Section and (n comments			
ver's COMMENTS	the transmittel form.						
JER 3 COMMENTS							
0:	DATE	7 1 .	(b)(6)				
O: (2) NV (1)	1 77 2 2 2 2	/11/11/ OCT LOIY	(b)(6)				
9	PROJ. SPEC. SECT. & PARA. and/or PROJ. DWG. NO. 09 83 13 para 1.2. para 2.1. Para 2.1.A. Para 2.1.D. para 2.2 para 1.2. para 1.2. para 1.2. para 1.2. para 1.2. para 1.2.	*List only one of the following categories and indicate which is being ractor Approved PROJ. SPEC. SECT. A PARA. and/or PROJ. DWG. NO. 98 83 13 PACOUSTICAL WAll Treatment brochura ACOUSTICAL WAll Treatment brochura PROJ. SPEC. SECT. A PARA. and/or PROJ. DWG. NO. 98 83 13 PACOUSTICAL WAll Treatment brochura ACOUSTICAL WAll Treatment Conwed Designscape - Repanels Deviation #1, Panel width: plan detail sheet A-402 call submitting 18"x18" in this submitted is 100% polyester. Color: Sample provided, room finish schedule, plan para 1.2. SD-04, Product samples PACTOR'S COMMENTS CEIVED BY REVIEWER FROM (Reviewer) List only one details alterillon to and indicated. Approval of an ontract requirements unless the contractor calls attention to	PROJ. SPEC. SECT. A PARA. and/or PROJ. DWG. NO. O9 83 13 Acoustical Wall Treatment para 1.2. SD-02, Shop drawings para 2.1. SD-03, Product data Conwed Designscape - Respond ACT acoustical panels Deviation #1, Panel width: Specs call for 24"x24", plan detail sheet A-402 call for 18"x18". We are submitting 18"x18" in this submittal. Deviation #2, Fabric covering: Spec call for 58% polyolefin and 42% post-consumer recycled polyester. Para 2.1.D. Color: Sample provided, Maharam, matches room finish schedule, plan sheet A-602 para 1.2. SD-04, Product samples CONTRACTOR REPRESENTA CEIVED BY REVIEWER FROM (Reviewer) Unbmittels are returned with action indicated. Approval of an item does not include approval of ontract requirements unless the contractor calls attention to and supports the deviation. Unbmittels are forwarded to LANTDIV with A-E recommendations indicated in ReviewER USE O	"List only one of the following categories on each transmittal form. and indicate which is being submitted "actor Approved OICC Approval Deviation/Substitution For OICC Approval For OICC Approval PROJ. SPEC. SECT. A PARA. and/or PROJ. DWG. NO. 1	**List only one of the following categories on each transmittal form. and indicate which is being submitted **A-Approved** OICC Approval		







From: (b)(6)

To: NAVFAC MIDLANT, ROICC Camp Lejeune; (b) (6) NAVFAC MIDLANT, ROICC

Camp Lejeune: (b)(6) NAVFAC MIDLANT, ROICC Camp Lejeune
(b)(6) (PM, Group III Management)

Cc: (b)(6) (PM, Gr Subject: [Non-DoD Source] FW: INDOOR/OUTDOOR CAT-6 CABLE

Date: Thursday, June 02, 2016 10:25:27

Attachments: in out c6 cable.pdf

Good morning. Below is Base Telephone's approval of an outdoor-rated CAT-6 cable we intend on using at the CLEO building. My QC Manager will submit this product data sheet today but with (b)(6) prior approval of the material I am authorizing my sub to install it tomorrow (3Jun). Thanks. R/

(b)(6) | Deputy Project Manager & Small Business Liaison | |

311 Parachute Tower Road | Camp Lejeune, NC 28542 |

Phone: w (b)(6) | c(b)(6) | Email:(b)(6)

Dragados USA, Inc. is An Equal Opportunity Employer

-----Original Message-----

From (b)(6) M [mailto(b)(6)

Sent: Thursday, June 02, 2016 10:02 AM

To: (b)(6) Cc: (b)(6)

(b)(c)

Subject: RE: INDOOR/OUTDOOR CAT-6 CABLE

(b)(6)

The attached product data sheet is acceptable to Base Telephone for the

conduit running through the slab at the CLEO building, but only the ROICC can

approve.

I can only advise and recommend but have no approval authority, please contact

the CM or ET for proper submittal procedures on the attached ...

Base Telephone Building 25 ----Original Message----From (b)(6) $[\underline{\text{mailto}}(b)(6)$ < mailto (b)(6 Sent: Thursday, June 02, 2016 9:47 AM (PM, Group III Cc: (b)(6) < mailto (b)(6) Management) Subject: [Non-DoD Source] INDOOR/OUTDOOR CAT-6 CABLE Good afternoon (b)(6) Would you please review that attached product data sheet and advise if this is acceptable for the conduit running through the slab at the CLEO building? Thanks. R. (b) | Deputy Project Manager & Small Business Liaison | | 311 Parachute Tower Road | Camp Lejeune, NC 28542 | Phone: w | Email: (b)(6) < mailto (b)(6)

Lead Investigator / Inspector / IT Project Manager

Dragados USA, Inc. is An Equal Opportunity Employer



Comtran Cable LLC 330A Turner Street South Attleboro, MA 02703-7714 (P) 508-399-7004 (F) 508-399-7360 www.ComtranCorp.com

Design Specification 35952

Category 6 Indoor/Outdoor LSZH CM-LS

Construction:

* Conductors: 23 AWG Solid Bare Copper per ASTM B-3

* Insulation: Polyethylene

* Pair Assembly: Color Coded Conductors Twisted to Varying Lays

* Cable Assembly: 4 Pairs Cabled With a LSZH X-Web

* Flooding Compound * Jacket: Black LSZH

Nominal OD = .290"

<u>Features:</u>

- * Prevents Against Moisture Migration
- * Superior 4 pair Balance for Increased Margins
- * Exceeds the Limited 50 ft. Entrance of Standard OSP Cables
- * Excellent Cross Talk characteristics

Compliance:

- * ETL Verified ANSI/TIA-568-C.2 Cat 6
- * UL Subject 444 Communications Cables
- * UL Listed type CM-LS
- * Sunlight Resistant Per UL 2556
- * NEC Article 800
- * ICEA S-90-661
- * California State Fire Marshal
- * RoHS Compliant
- * Voltage Rating 300

Common Applications:

- * Gigabit Ethernet (1000Base-T)
- * Multimedia & ISDN
- * High Speed Voice/Data applications
- * 1.2 Gbps Ethernet
- * Broadband Video

Category 6 Electricals

Return NEXT PSNEXT ACRF PSACRF Char. Impedance Attenuation Loss Freq. (dB) (dB/100m)(dB/100m)(dB/100m)(dB/100m)(dB/100m)(Ohms) (MHz.) (+/-15)(Min) (Max) (Min) (Min) (Min) (Min) 72.3 64.8 100 20 74.3 67.8 63.3 52.8 4 100 23 3.8 65.3 55.8 58.8 46.7 49.7 8 100 24.5 5.3 60.8 57.3 10 100 25 6 59.3 47.8 16 100 25 7.6 56.2 54.2 43.7 40.7 52.8 38.8 20 100 25 8.5 54.8 41.8 51.3 25 100 24.3 9.5 53.3 39.8 36.8 49.9 34.9 31.25 100 23.6 10.7 51.9 37.9 45.4 28.9 62.5 100 21.5 15.4 47.4 31.9 42.3 24.8 27.8 100 100 20.1 19.8 44.3 19.4 40.9 22.8 42.9 25.8 125 100 22.4 39.4 20.9 155 100 18.8 25.2 41.4 23.9 38.7 19.9 175 40.7 22.9 100 18.4 26.9 37.8 188 200 100 18 29 39.8 21.8 36.3 16.8 19.8 250 100 17.3 32.8 38.3

Print: COMTRAN CABLE LLC COM-LINK INDOOR/OUTDOOR CAT 6 250 MHZ 23 AWG CM-LS C(UL)US SUNLIGHT RESISTANT ETL VERIFIED TO ANSI/TIA-568-C.2 CATEGORY 6 ROHS (01-12345) 000002

DRAWING	REV.	DATE	DRWN.	APP.	REMARKS	
						35952
						Dogg 1 of 1
35952	01	8/6/14	BAL	Љ	Initial Release	Page 1 of 1



Comtran Cable LLC 330A Turner Street South Attleboro, MA 02703-7714 (P) 508-399-7004 (F) 508-399-7360 www.ComtranCorp.com

Design Specification 35952

Category 6 Indoor/Outdoor LSZH CM-LS

Construction:

* Conductors: 23 AWG Solid Bare Copper per ASTM B-3

* Insulation: Polyethylene

* Pair Assembly: Color Coded Conductors Twisted to Varying Lays

* Cable Assembly: 4 Pairs Cabled With a LSZH X-Web

* Flooding Compound * Jacket: Black LSZH

Nominal OD = .290"

<u>Features:</u>

- * Prevents Against Moisture Migration
- * Superior 4 pair Balance for Increased Margins
- * Exceeds the Limited 50 ft. Entrance of Standard OSP Cables
- * Excellent Cross Talk characteristics

Compliance:

- * ETL Verified ANSI/TIA-568-C.2 Cat 6
- * UL Subject 444 Communications Cables
- * UL Listed type CM-LS
- * Sunlight Resistant Per UL 2556
- * NEC Article 800
- * ICEA S-90-661
- * California State Fire Marshal
- * RoHS Compliant
- * Voltage Rating 300

Common Applications:

- * Gigabit Ethernet (1000Base-T)
- * Multimedia & ISDN
- * High Speed Voice/Data applications
- * 1.2 Gbps Ethernet
- * Broadband Video

Category 6 Electricals

Return NEXT PSNEXT ACRF PSACRF Char. Impedance Attenuation Loss Freq. (dB) (dB/100m)(dB/100m)(dB/100m)(dB/100m)(dB/100m)(Ohms) (MHz.) (+/-15)(Min) (Max) (Min) (Min) (Min) (Min) 72.3 64.8 100 20 74.3 67.8 63.3 52.8 4 100 23 3.8 65.3 55.8 58.8 46.7 49.7 8 100 24.5 5.3 60.8 57.3 10 100 25 6 59.3 47.8 16 100 25 7.6 56.2 54.2 43.7 40.7 52.8 38.8 20 100 25 8.5 54.8 41.8 51.3 25 100 24.3 9.5 53.3 39.8 36.8 49.9 34.9 31.25 100 23.6 10.7 51.9 37.9 45.4 28.9 62.5 100 21.5 15.4 47.4 31.9 42.3 24.8 27.8 100 100 20.1 19.8 44.3 19.4 40.9 22.8 42.9 25.8 125 100 22.4 39.4 20.9 155 100 18.8 25.2 41.4 23.9 38.7 19.9 175 40.7 22.9 100 18.4 26.9 37.8 188 200 100 18 29 39.8 21.8 36.3 16.8 19.8 250 100 17.3 32.8 38.3

Print: COMTRAN CABLE LLC COM-LINK INDOOR/OUTDOOR CAT 6 250 MHZ 23 AWG CM-LS C(UL)US SUNLIGHT RESISTANT ETL VERIFIED TO ANSI/TIA-568-C.2 CATEGORY 6 ROHS (01-12345) 000002

DRAWING	REV.	DATE	DRWN.	APP.	REMARKS	
						35952
						Dogg 1 of 1
35952	01	8/6/14	BAL	Љ	Initial Release	Page 1 of 1

From: NAVFAC MIDLANT, ROICC Camp Lejeune

To: NAVFAC MIDLANT, IPTMC

Cc: NAVFAC MIDLANT, ROICC Camp Leieune; (b) (6) NAVFAC MIDLANT, IPTMC;

NAVEAC MIDLANT, CI (b) (6) NAVEAC MIDLANT, IPTMC

Subject: RE: P-1383 [Non-DoD Source] Re: PRELIMINARY CLEO TAB REPORT

Date: Thursday, May 26, 2016 7:00:00

Hi all, sorry, just getting caught up on all my emails. How sad is that!

It was my understanding that Dragados would put in the equipment as designed, and we would see how the results came in after that. Is that still where we are with this? Their ultimate CCD is still in September, so we have a bit of time (not a ton though!).

They are trying to get out of there as fast as possible, so yes, we'll have to keep an eye on them!

R/ (b)(6)

(b)(6)
Contract Specialist
ROICC Camp Lejeune
(b)(6)
DSN (b)
(b)(6) fax
(b)(6)

----Original Message----

From: (b)(6) NAVFAC MIDLANT, IPTMC

Sent: Thursday, May 19, 2016 9:55 AM

To: (b)(6) NAVFAC MIDLANT, ROICC Camp Lejeune

Cc (b)(6) NAVFAC MIDLANT, ROICC Camp Lejeune; (b)(6) NAVFAC MIDLANT, IPTMC; (b)(6) NAVFAC MIDLANT, CI; (b)(6) NAVFAC

MIDLANT, IPTMC

Subject: FW: P-1383 [Non-DoD Source] Re: PRELIMINARY CLEO TAB REPORT

(b)(6)

I am not sure how urgent this item is. Based on my conversations with (b), he stills feels the DOR is correct and the contractor is misrepresenting the information. I have asked my mechanical engineer to weigh in, but he out of the office and may not be able to respond until next week. If he agrees with the DOR and (b), we will be back were we were months ago, and directing the contractor to install as per the plans.

(b)

(b)(6), P.E.

Civil Engineer

NAVFAC MIDLANT

Marine Corps IPT

*Building Z-140, Room 104

*9324 Virginia Avenue

*Norfolk, VA 23511-3095

Phone: (b)(6)

Fax: (b)(6

Email: (b)(6)

```
----Original Message----
               [mailto
From: (b)(6)
Sent: Tuesday, May 17, 2016 12:14 PM
To: (b)(6)
                    NAVFAC MIDLANT, CI;
                                                               NAVFAC MIDLANT, ROICC Camp
Lejeune; (b)(6)
                                                   NAVFAC MIDLANT, ROICC Camp Lejeune;
                        NAVFAC MIDLANT, ROICC Camp Lejeune: (b)(6)
      NAVFAC MIDLANT, ROICC Camp Lejeune, (b) (6)
                        (Group III Mgt.);
                                                       (Group III Mgt Superintendent):(b)(6)
Cc
                                         NAVFAC MIDLANT, IPTMC
Subject: [Non-DoD Source] Re: PRELIMINARY CLEO TAB REPORT
Please see the attached TAB response from GIII.
Thank you -
          - Vice President
(b)(6)
Group III Mgt., Inc.
Cell (b) (6)
Office: (b)
Fax: (b)(6
----Original Message----
From (b)(6)
                      NAVFAC MIDLANT, CI
Sent: Monday, May 16, 2016 4:55 PM
To: (b)(b)
                      NAVFAC MIDLANT, ROICC Camp Lejeune; (b)(6)
         NAVFAC MIDLANT, ROICC Camp Lejeune; (b)(6)
                                                                            NAVFAC MIDLANT,
ROICC Camp Lejeune; (b)(6)
                                                                     NAVFAC MIDLANT, ROICC
Camp Lejeune ;(b)(6)
                                                    (PM, Group III
Cc: (b)(6)
                        (Group III Mgt.) (b)(6)
Management); (b)(6)
                            (Group III Mgt Superintendent) (b)(6)
                      NAVFAC MIDLANT, IPTMC
Subject: RE: PRELIMINARY CLEO TAB REPORT
All,
For continued surveillance of mechanical design issues, please keep the assigned NAVFAC ML Mechanical
Engineer copied on all mechanical design-related correspondence by including (b)(6) , copied on this email
Respectfully,
         , EIT, PMP
Mechanical Acceptance Engineer
                            CELL (b)(6)
                                               / FAX (b)
----Original Message-----
From (b)(6)
                         NAVFAC MIDLANT, ROICC Camp Lejeune
Sent: Monday, May 16, 2016 1:38 PM
                                                NAVFAC MIDLANT, CI; (b)(6)
                                                       NAVFAC MIDLANT, ROICC Camp Lejeune;
MIDLANT, ROICC Camp Lejeune; (b) (6)
                                                NAVFAC MIDLANT, ROICC Camp Lejeune; (b)(6)
```



Hi all -


Sorry to jump in as I am a non-technical person. I just spoke with (b)

Dragados will put in the equipment per the original design. However, this is design-bid-build. From a contracting perspective, should the equipment, if all is installed per the plans, still does not meet the required airflows, this is not the Contractor's responsibility any longer, but a design issue.

When the Contractor is not responsible for the design, we cannot hold him responsible for airflows if everything is installed per the A/E design. I believe and I are in agreement that if the CLEO is built per the plans, we will not hold up BOD for design issues. If there are any design changes, they need to be made ASAP if Dragados is intended to perform them.

Otherwise, another contract will have to follow to correct after BOD.

Subject: [Non-DoD Source] RE: PRELIMINARY CLEO TAB REPORT




When you first told me about this I told you I needed to see the TAB report to see if we were in tolerance and we're not. An RFI was asked about this a while back and we stated in that RFI that HP-1 was HP-1 and HP-2 was HP-2. The airflows on the schedule match the total airflow of all the diffusers for each unit. As I told you the cooling

HP-2 has more outside air than HP-1. If you look at the sensible load on the schedule you will see that HP-1 has a higher sensible load than HP-2.

Sincerely,

capacity for HP-2 is higher because





Subject: RE: PRELIMINARY CLEO TAB REPORT

you've known for weeks that HP1 and HP2 are reversed. I told you this myself. They were reversed by my subcontractor based off of the numbers for the total cooling capacity for HPs 1&2 shown on WM602. If your position is that you want to see HP1 &HP2 installed per the plan then our request to NAVFAC is that you produce data from your calculations that this configuration will achieve what you want given HP sizes of 3.5 and 4.9. I am on my way over to NAVFAC now to discuss this. Thanks. R/

(b)(6) | Deputy Project Manager & Small Business Liaison | cid:image001.png@01CCA871.8C8E7960 |

311 Parachute Tower Road | Camp Lejeune, NC 28542 |

Phone: w(b)(6) c(b)(6) | Email: (b)(6) | Email: (b)(6) | Cmailto (b)(6) | Email: (b)(6) | Cmailto (b)(6) | Cmailto (b)(6) | Email: (b)(6) | Cmailto (b)(6) | Email: (b)(6) | Email: (b)(6) | Cmailto (b)(6) | Email: (b)(6) |

Dragados USA, Inc. is An Equal Opportunity Employer

**** Confidential *****

This electronic message transmission contains information from Dragados USA Inc., that may be confidential or privileged. The information is intended to be for the use of only the individual or entity named above and not to be distributed to other companies or individuals. If you are not the intended recipient, be aware that any disclosure, copying, distribution or use of the contents of this information is strictly prohibited. If you have received this electronic transmission in error, please notify the sender by reply e-mail immediately and delete this e-mail and any attachments from your system and any copies you may have made, electronic or otherwise.

From: (b)(6) [mailto(b)(6)
Sent: Monday, May 16, 2016 11:50 AM

```
To (b)(6)
(b)(6)
(NAVFAC Contract Spec); (b)(6)
(b)(6)
(c: (b)(6)
Group III (b)(6)
(PM, Group III Management); (b)(6)
(Group III Mgt Superintendent): (b)(6)
Subject: RE: PRELIMINARY CLEO TAB REPORT
```

(b)(6)

The only issues we see is HP-1 was installed as HP-2 and vice versa. This is causing the units to not meet the design airflows. Recommend installing the heat pumps as shown on the contract drawings. Also for the next TAB report please provide each heat pump airflows on high and low speed.

Sincerely,

From: (b)(6)

(b)(6), P.E., CxA, LEED AP BD+C
CEMS Engineering Inc.
(b)(6)
Office (b)(6)
Cell (b)(6)

Sent: Monday, May 16, 2016 11:28 AM

To: (b)(6)
(NAVFAC)(b)(6)
(b)(6)
(b)(6)
(c: (b)(6)
(Cc: (b)(6)
(FM, Group III Management) (b)(6)
(Group III Mgt.)(b)(6)
(Group III Mgt.)(b)(6)

Subject: RE: PRELIMINARY CLEO TAB REPORT

<u>mailto:(b)(6)</u>

Re-sending this email (b)(6) is out on leave and won't return until 6Jun. I request to find out from (b)(6) (CEMS) and (b)(6) (NAVFAC Norfolk) you thoughts on the initial TAB performance results (HP-1 is at 85% of design). We will be performing TAB again once we replace dampers in the CLEO. Thanks.

I do not think that the TAB results will change too much after we install the new dampers. I am confused by

the specs: are heat pumps held to \pm 5% tolerance? The specs states this is the case for groups 2 & 3. Heat pumps are in ground 1.

If the heat pumps, as installed, aren't accepted at 85% of design we will request CEMS runs their model again using the data shown on WM602 (attached) before we take additional steps. We think the 2 high-lighted numbers may be inadvertently reversed. Thanks. R/(b)

SPEC 23 05 93, page 1: Out-of-tolerance data: Pertains only to field acceptance testing of Final TAB report. When applied to TAB work this phase means "a measurement taken during TAB field acceptance testing which does not fall within the range of plus 5 to minus 5 percent of the original measurement reported on the TAB Report for a specific parameter."

3.3.9.1 TAB Field Acceptance Testing

During the field acceptance testing, verify, in the presence of the COTR, random selections of data (water, air quantities, air motion,) recorded in the TAB Report. Points and areas for field acceptance testing are to be selected by the COTR. Measurement and test procedures are the same as approved for TAB work for the TAB Report.

Field acceptance testing includes verification of TAB Report data recorded for the following equipment groups:

- Group 1: All heat pumps and pumps.
- Group 2: 25 percent of the return grilles, return registers, exhaust grilles and exhaust registers.
- Group 3: 25 percent of the exhaust fans.

Further, if any data on the TAB Report for Groups 2 through 3 is found not to fall within the range of plus 5 to minus 5 percent of the TAB Report data, additional group data verification is required in the presence of the COTR. Verify TAB Report data for one additional piece of equipment in that group. Continue this additional group data verification until out-of-tolerance data ceases to be found.

Good afternoon (b) Attached is an executive summary of the CLEO TAB.

All items are within 5% of design max CFM except for HP-1. It is at 85%, or 15% shy. The design CFM for HP1 is 1100 (min) to 1450 (max). The actual reading during tab was 1231.

We will be performing TAB again once we replace dampers in the CLEO. We welcome your response to this preliminary TAB. Thanks. R(b)(6)

(b)(6) | Deputy Project Manager & Small Business Liaison | cid:image001.png@01CCA871.8C8E7960 |

311 Parachute Tower Road | Camp Lejeune, NC 28542 |

Phone: w (b)(6) | c (b)(6) | Email: (b)(6) | C (mailto(b)(6) | Email: (b)(6) | Email: (c)(6) | Email: (d)(6) |

Dragados USA, Inc. is An Equal Opportunity Employer

**** Confidential *****

This electronic message transmission contains information from Dragados USA Inc., that may be confidential or privileged. The information is intended to be for the use of only the individual or entity named above and not to be distributed to other companies or individuals. If you are not the intended recipient, be aware that any disclosure, copying, distribution or use of the contents of this information is strictly prohibited. If you have received this electronic transmission in error, please notify the sender by reply e-mail immediately and delete this e-mail and any attachments from your system and any copies you may have made, electronic or otherwise.

From: (b)(6) [mailto(b)(6)

Sent: Tuesday, May 03, 2016 9:48 AM


To: (b)(6) (NAVFAC): (b)(6)
(b)(6) (PM, Group III Mgt.); (b)(6) (PM, Group III Management)

Subject: RE: PRELIMINARY CLEO TAB REPORT

(b)(6)

Please provide an executive summary at the front of the report showing all items not within specification.

Sincerely,



Attached is the TAB field report. Please forward this to (b)(6) for his review and comments. We are sending this to our commissioning agent for his review and comments also (he is copied on this email).

Please let us know what (b)(6) comments are as soon as possible so we can schedule the commissioning work.

----Original Message-----

From: (b)(6)

Sent: Wednesday, April 20, 2016 11:09 AM

To: (b)(6)

Subject: FW: 224887 Field TAB Report

(b)(6)

Raleigh Division Manager / NEBB Professional

NAVFAC MIDLANT, ROICC Camp Lejeune To: NAVFAC MIDLANT, ROICC Camp Lejeune Cc: NAVFAC MIDLANT, IPTMC; NAVFAC MIDLANT, CI (b) (6) NAVFAC MIDLANT, IPTMC RE: P-1383 [Non-DoD Source] Re: PRELIMINARY CLEO TAB REPORT Subject: Date: Thursday, May 26, 2016 12:55:18 I checked with (b) and (b) and they agree that we are waiting on Dragados to install and test the equipment. . P.E. Civil Engineer NAVFAC MIDLANT Marine Corps IPT *Building Z-140, Room 104 *9324 Virginia Avenue *Norfolk, VA 23511-3095 Phone: (b)(6) Fax: (b) Email: ----Original Message----From NAVFAC MIDLANT, ROICC Camp Lejeune Sent: Thursday, May 26, 2016 7:00 AM To: (b)(6) NAVFAC MIDLANT, IPTMC NAVFAC MIDLANT, ROICC Camp Lejeune; **NAVFAC NAVFAC** MIDLANT, IPTMC; (b) (6) NAVFAC MIDLANT, CI; MIDLANT, IPTMC Subject: RE: P-1383 [Non-DoD Source] Re: PRELIMINARY CLEO TAB REPORT Hi all, sorry, just getting caught up on all my emails. How sad is that! It was my understanding that Dragados would put in the equipment as designed, and we would see how the results came in after that. Is that still where we are with this? Their ultimate CCD is still in September, so we have a bit of time (not a ton though!). They are trying to get out of there as fast as possible, so yes, we'll have to keep an eye on them! R/

NAVFAC MIDLANT, IPTMC



From:

```
NAVFAC MIDLANT, IPTMC
From: (b)(6)
Sent: Thursday, May 19, 2016 9:55 AM
                       NAVFAC MIDLANT, ROICC Camp Lejeune
Cc
                   NAVFAC MIDLANT, ROICC Camp Lejeune;
                                                                                  NAVFAC
MIDLANT, IPTMC;
                                    NAVFAC MIDLANT, CI;
                                                                                  NAVFAC
MIDLANT, IPTMC
Subject: FW: P-1383 [Non-DoD Source] Re: PRELIMINARY CLEO TAB REPORT
I am not sure how urgent this item is. Based on my conversations with how, he stills feels the DOR is correct and
the contractor is misrepresenting the information. I have asked my mechanical engineer to weigh in, but he out of
the office and may not be able to respond until next week. If he agrees with the DOR and b, we will be back
were we were months ago, and directing the contractor to install as per the plans.
            , P.E.
Civil Engineer
NAVFAC MIDLANT
Marine Corps IPT
*Building Z-140, Room 104
*9324 Virginia Avenue
*Norfolk, VA 23511-3095
Phone:(b)(6)
Fax: (b
Email:
----Original Message-----
From: (b)(6)
                [<u>mailto:</u>(b)(6)
Sent: Tuesday, May 17, 2016 12:14 PM
To (b)(6)
                    NAVFAC MIDLANT, CI; (b) (6)
                                                                 NAVFAC MIDLANT, ROICC Camp
                                                     NAVFAC MIDLANT, ROICC Camp Lejeune;
Lejeune; (b)(6)
                         NAVFAC MIDLANT, ROICC Camp Lejeune; (b)(6)
      NAVFAC MIDLANT, ROICC Camp Lejeune; (b)(6
                         (Group III Mgt.);
                                                        (Group III Mgt Superintendent); (b)(6)
Cc: (b)(6)
                                          NAVFAC MIDLANT, IPTMC
Subject: [Non-DoD Source] Re: PRELIMINARY CLEO TAB REPORT
Please see the attached TAB response from GIII.
Thank you -
            Vice President
Group III Mgt., Inc.
Cell: (b)(6)
Office:
Fax: (b) (6
-----Original Message--
                       NAVFAC MIDLANT, CI
From: (b)(6)
Sent: Monday, May 16, 2016 4:55 PM
                       NAVFAC MIDLANT, ROICC Camp Lejeune; (b)(6)
          NAVFAC MIDLANT, ROICC Camp Lejeune :
                                                                             NAVFAC MIDLANT,
ROICC Camp Lejeune ;(b)(6)
                                                                       NAVFAC MIDLANT, ROICC
Camp Lejeune ; (b)(6)
                         (Group III Mgt.) (b)(6)
                                                     (PM, Group III
```

Management): (Group III Mgt Superintendent) : (6) NAVFAC MIDLANT, IPTMC Subject: RE: PRELIMINARY CLEO TAB REPORT All, For continued surveillance of mechanical design issues, please keep the assigned NAVFAC ML Mechanical Engineer copied on all mechanical design-related correspondence by including Steve Medvick, copied on this email Respectfully, , EIT, PMP Mechanical Acceptance Engineer / DSN: (b)(6) / FAX: / CELL ----Original Message----NAVFAC MIDLANT, ROICC Camp Lejeune From: Sent: Monday, May 16, 2016 1:38 PM NAVFAC MIDLANT, CI. (b) (6) NAVFAC MIDLANT, ROICC Camp Lejeune; (b)(6) NAVFAC MIDLANT, ROICC Camp Lejeune; (PM, Group III Management):(b)(6) (Group III Mgt.) (Group

Hi all -

III Mgt Superintendent);

Sorry to jump in as I am a non-technical person. I just spoke with (b)(6)


Subject: RE: PRELIMINARY CLEO TAB REPORT

Dragados will put in the equipment per the original design. However, this is design-bid-build. From a contracting perspective, should the equipment, if all is installed per the plans, still does not meet the required airflows, this is not the Contractor's responsibility any longer, but a design issue.

When the Contractor is not responsible for the design, we cannot hold him responsible for airflows if everything is installed per the A/E design. I believe and I are in agreement that if the CLEO is built per the plans, we will not hold up BOD for design issues. If there are any design changes, they need to be made ASAP if Dragados is intended to perform them.

Otherwise, another contract will have to follow to correct after BOD.

R/ (b)(6)



```
From: (b)(6) [mailto(b)(6)]

Sent: Monday, May 16, 2016 12:39 PM

To: (b)(6) NAVFAC MIDLANT, CI; (b)(6) NAVFAC MIDLANT, ROICC Camp Lejeune; (b)(6)

(b)(6) NAVFAC MIDLANT, ROICC Camp Lejeune; (b)(6)

(b) NAVFAC MIDLANT, ROICC Camp Lejeune; (b)(6)

(c) NAVFAC MIDLANT, ROICC Camp Lejeune; (b)(6)

(d) NAVFAC MIDLANT, ROICC Camp Lejeune; (b)(6)

(e) (Group III Mgt.); (b)(6) (PM, Group III Management); (b)(6)

Subject: [Non-DoD Source] RE: PRELIMINARY CLEO TAB REPORT
```

When you first told me about this I told you I needed to see the TAB report to see if we were in tolerance and we're not. An RFI was asked about this a while back and we stated in that RFI that HP-1 was HP-1 and HP-2 was HP-2. The airflows on the schedule match the total airflow of all the diffusers for each unit. As I told you the cooling capacity for HP-2 is higher because

HP-2 has more outside air than HP-1. If you look at the sensible load on the schedule you will see that HP-1 has a higher sensible load than HP-2.

Sincerely,

(NAVFAC) (b) (6

Superintendent) (b) (6)

```
CEMS Engineering Inc.

(b)(6)

Office(b)(6)

Cell(b)(6)

From: (b)(6) [mailto:(b)(6) ]

Sent: Monday, May 16, 2016 12:30 PM

To: (b)(6)
```

, P.E., CxA, LEED AP BD+C

Subject: RE: PRELIMINARY CLEO TAB REPORT

(PM, Group III Management) (b)

(b)(6) you've known for weeks that HP1 and HP2 are reversed. I told you this myself. They were reversed by my subcontractor based off of the numbers for the total cooling capacity for HPs 1&2 shown on WM602. If your position is that you want to see HP1 &HP2 installed per the plan then our request to NAVFAC is that you produce

(Group III Mgt.)

(NAVFAC Contract Spec)

(Group III Mgt

data from your calculations that this configuration will achieve what you want given HP sizes of 3.5 and 4.9. I am on my way over to NAVFAC now to discuss this. Thanks. R/

(b)(6) | Deputy Project Manager & Small Business Liaison | cid:image001.png@01CCA871.8C8E7960 |


311 Parachute Tower Road | Camp Lejeune, NC 28542 |

Phone: w (b)(6) | c (b)(6) | Email: (b)(6) | Email: (b)(6) | |

Dragados USA, Inc. is An Equal Opportunity Employer

**** Confidential *****

This electronic message transmission contains information from Dragados USA Inc., that may be confidential or privileged. The information is intended to be for the use of only the individual or entity named above and not to be distributed to other companies or individuals. If you are not the intended recipient, be aware that any disclosure, copying, distribution or use of the contents of this information is strictly prohibited. If you have received this electronic transmission in error, please notify the sender by reply e-mail immediately and delete this e-mail and any attachments from your system and any copies you may have made, electronic or otherwise.



(b)(6)

The only issues we see is HP-1 was installed as HP-2 and vice versa. This is causing the units to not meet the design airflows. Recommend installing the heat pumps as shown on the contract drawings. Also for the next TAB report please provide each heat pump airflows on high and low speed.

Sincerely,

(b)(6), P.E., CxA, LEED AP BD+C

CEMS Engineering Inc.

(b)(6)

Office (b)(6)
Cell (b)(6)

From: (b)(6) [mailto (b)(6)]

Sent: Monday, May 16, 2016 11:28 AM

To: (b)(6) (NAVFAC) (b)(6)
(b)(6) (NAVFAC Contract Spec)
(b)(6) (Group III Mgt.) (b)(6)

(Group III Mgt.) (Group III Mgt.)

Superintendent) (b)(6)

Subject: RE: PRELIMINARY CLEO TAB REPORT

Re-sending this email. (b)(6) is out on leave and won't return until 6Jun. I request to find out from (b)(6) (CEMS) and (b)(6) (NAVFAC Norfolk) you thoughts on the initial TAB performance results (HP-1 is at 85% of design). We will be performing TAB again once we replace dampers in the CLEO. Thanks.

, I do not think that the TAB results will change too much after we install the new dampers. I am confused by the specs: are heat pumps held to +/- 5% tolerance? The specs states this is the case for groups 2 & 3. Heat pumps are in ground 1.

If the heat pumps, as installed, aren't accepted at 85% of design we will request CEMS runs their model again using the data shown on WM602 (attached) before we take additional steps. We think the 2 high-lighted numbers may be inadvertently reversed. Thanks. R/(b)(6)

SPEC 23 05 93, page 1: Out-of-tolerance data: Pertains only to field acceptance testing of Final TAB report. When applied to TAB work this phase means "a measurement taken during TAB field acceptance testing which does not fall within the range of plus 5 to minus 5 percent of the original measurement reported on the TAB Report for a specific parameter."

3.3.9.1 TAB Field Acceptance Testing

During the field acceptance testing, verify, in the presence of the COTR, random selections of data (water, air quantities, air motion,) recorded in the TAB Report. Points and areas for field acceptance testing are to be selected by the COTR. Measurement and test procedures are the same as approved for TAB work for the TAB Report.

Field acceptance testing includes verification of TAB Report data recorded for the following equipment groups:

Group 1: All heat pumps and pumps.

Group 2: 25 percent of the return grilles, return registers, exhaust grilles and exhaust registers.

Group 3: 25 percent of the exhaust fans.

Further, if any data on the TAB Report for Groups 2 through 3 is found not to fall within the range of plus 5 to minus 5 percent of the TAB Report data, additional group data verification is required in the presence of the COTR. Verify TAB Report data for one additional piece of equipment in that group. Continue this additional group data verification until out-of-tolerance data ceases to be found.

Good afternoon (b). Attached is an executive summary of the CLEO TAB.

All items are within 5% of design max CFM except for HP-1. It is at 85%, or 15% shy. The design CFM for HP1 is 1100 (min) to 1450 (max). The actual reading during tab was 1231.

We will be performing TAB again once we replace dampers in the CLEO. We welcome your response to this preliminary TAB. Thanks. R(b)(6)

(b)(6) | Deputy Project Manager & Small Business Liaison | cid:image001.png@01CCA871.8C8E7960 |

311 Parachute Tower Road | Camp Lejeune, NC 28542 |

Phone: w (b)(6) | c(b)(6) | Email: (b)(6) | Email: (b)(6) | |

Dragados USA, Inc. is An Equal Opportunity Employer

**** Confidential *****

This electronic message transmission contains information from Dragados USA Inc., that may be confidential or privileged. The information is intended to be for the use of only the individual or entity named above and not to be distributed to other companies or individuals. If you are not the intended recipient, be aware that any disclosure, copying, distribution or use of the contents of this information is strictly prohibited. If you have received this electronic transmission in error, please notify the sender by reply e-mail immediately and delete this e-mail and any attachments from your

system and any copies you may have made, electronic or otherwise.

From: (b)(6) [mailto (b)(6)]

Sent: Tuesday, May 03, 2016 9:48 AM

To (b)(6) (NAVFAC); (b)(6) (Oroup III Mgt.); (b)(6) (PM, Group III Management)

Subject: RE: PRELIMINARY CLEO TAB REPORT

(b)(6)

Please provide an executive summary at the front of the report showing all items not within specification.

Sincerely,

(b)(6), P.E., CxA, LEED AP BD+C CEMS Engineering Inc.

(b)(6)

Office(b)(6)

Cell(b)(6)

From: (b)(6) [mailto(b)(6)]

Sent: Monday, May 2, 2016 5:28 PM

To: (b)(6) (NAVFAC)(b)(6) (b)(6) (Group III Mgt.) (D)(6) (PM, Group III Management) (b)(6)

Subject: PRELIMINARY CLEO TAB REPORT

Importance: High

Good afternoon . Attached is the preliminary TAB report for the CLEO building. Request your early review and comments. My team is available for a phone call if you think discussing your thoughts would help. Thanks. R/

(b)(6)

Deputy Project Manager & Small Business Liaison | |

311 Parachute Tower Road | Camp Lejeune, NC 28542 |

Phone: w (b)(6) | c (b)(6) | Email (b)(6) |

<mailto(b)(6) |

Dragados USA, Inc. is An Equal Opportunity Employer

-----Original Message-----

(b)(6)

From: (b)(6)

Attached is the TAB field report. Please forward this to (b)(6) for his review and comments. We are sending this to our commissioning agent for his review and comments also (he is copied on this email).

[<u>mailto:</u>(b)(6)

Sent: Wednesday, April 20, 2016 1:58 PM

Subject: Fw: 224887 Field TAB Report CLEO

Please let us know what (b)(6) comments are as soon as possible so we can schedule the commissioning work.

----Original Message----

From (b)(6)

Sent: Wednesday, April 20, 2016 11:09 AM

To: (b)(6)

Subject: FW: 224887 Field TAB Report

(b)(6)

Raleigh Division Manager / NEBB Professional

From: NAVFAC MIDLANT, IPTMC

To: NAVFAC MIDLANT, ROICC Camp Lejeune

Cc: NAVFAC MIDLANT, ROICC Camp Lejeune; (b) (6) NAVFAC MIDLANT, IPTMC;

NAVFAC MIDLANT, CI; (b) (6) NAVFAC MIDLANT, IPTMC

Subject: RE: P-1383 [Non-DoD Source] Re: PRELIMINARY CLEO TAB REPORT

Date: Saturday, May 21, 2016 17:48:30

(b)(6)

As promised, I asked our mechanical engineer to provide some input (b) comments are below, but he seems to agree with (b)(6) in that the contractor's analysis is incomplete.



From: (b)(6) NAVFAC MIDLANT, IPTMC

Sent: Thursday, May 19, 2016 1:13 PM

To: (b)(6) NAVFAC MIDLANT, IPTMC

Cc: (b)(6) NAVFAC MIDLANT, IPTMC: (b)(6) NAVFAC MIDLANT, CI

Subject: RE: PRELIMINARY CLEO TAB REPORT (P-1383)

After review of the information provided, the following is offered by MCIPT:

- 1. We disagree that the product data (Attachment B) sets forth a pump that meets the design requirements for pump HP-1. Dispute is as follows:
- -Attachment B, page 1, product data sheet indicates that selected pump (39.9 MBH) meets/exceeds design cooling load requirement (37.0 MBH). However, it does not meet the design heating load requirement (29.2 MBH in product data, 33.7 in design).
- -Page 2, required design water flow of 12 GPM. Attachment B, page 2, does not set forth 12 gpm as an operating parameter.
- -Design entering air temperatures are 78 F DB/65 F WB for HP-1, 77 F DB/60.8 F WB for HP-2. Product data sheet states that cooling capacities are based on 80 DB/66.2 DB and heating capacities are based on 68 DB/59 WB. Clarification needed on how these correlate.
- -As stated by CI52, design requires a max cfm of 1450 for HP-1. Product data sets forth 1250 cfm. TAB report indicates HP-1 only attained 1231 cfm.
- 2. Group III cover letter states that attachment B also meets design requirements for HP-2. The following disputes this claim:
- -Page 1, design cooling load requirement (40.1 MBH) is met (40.3 MBH), but heating load requirement (37.8 MBH) is not (30.1 MBH).
- -Page 2, required design water flow is 9 GPM. For the selected pump to meet design requirements, entering water temperature would have to be 80 deg F or lower.

Conclusion is that neither pump meets the design requirements.

(b)(6), PE, CEM, GPCP, GGP Supervisory Mechanical Engineer NAVFAC MIDLANT MCIPT Ph (b)(6) Know the standard, follow the standard, enforce the standard

```
, P.E.
Civil Engineer
NAVFAC MIDLANT
Marine Corps IPT
*Building Z-140, Room 104
*9324 Virginia Avenue
*Norfolk, VA 23511-3095
Phone: (b)(6)
Fax:
Email:
----Original Message----
From: (b)
                            NAVFAC MIDLANT, IPTMC
Sent: Thursday, May 19, 2016 9:55 AM
To:
                       NAVFAC MIDLANT, ROICC Camp Lejeune
Cc:
                   NAVFAC MIDLANT, ROICC Camp Lejeune;
                                                                                 NAVFAC
MIDLANT, IPTMC;
                                                                                  NAVFAC
                                    NAVFAC MIDLANT, CI;
MIDLANT, IPTMC
Subject: FW: P-1383 [Non-DoD Source] Re: PRELIMINARY CLEO TAB REPORT
I am not sure how urgent this item is. Based on my conversations with (b) he stills feels the DOR is correct and
the contractor is misrepresenting the information. I have asked my mechanical engineer to weigh in, but he out of
the office and may not be able to respond until next week. If he agrees with the DOR and b, we will be back
were we were months ago, and directing the contractor to install as per the plans.
             , P.E.
Civil Engineer
NAVFAC MIDLANT
Marine Corps IPT
*Building Z-140, Room 104
*9324 Virginia Avenue
*Norfolk, VA 23511-3095
Phone: (b)(6)
Fax:
Email:
----Original Message-----
                [mailto(b)(6)
Sent: Tuesday, May 17, 2016 12:14 PM
                    NAVFAC MIDLANT, CI:(b)(6)
                                                                 NAVFAC MIDLANT, ROICC Camp
Lejeune; (b)(6)
                                                     NAVFAC MIDLANT, ROICC Camp Lejeune;
                         NAVFAC MIDLANT, ROICC Camp Lejeune: (b)(6)
      NAVFAC MIDLANT, ROICC Camp Lejeune; (b) (6)
                         (Group III Mgt.); (b)(6)
                                                        (Group III Mgt Superintendent): (b) (6)
                                          NAVFAC MIDLANT, IPTMC
Subject: [Non-DoD Source] Re: PRELIMINARY CLEO TAB REPORT
```

Please see the attached TAB response from GIII.


```
- Vice President
Group III Mgt., Inc.
Cell:
Office:
Fax: (b)(6
----Original Message----
From:
                       NAVFAC MIDLANT, CI
Sent: Monday, May 16, 2016 4:55 PM
To: (b)(6)
                       NAVFAC MIDLANT, ROICC Camp Lejeune;
          NAVFAC MIDLANT, ROICC Camp Lejeune; (b)(6)
                                                                            NAVFAC MIDLANT,
ROICC Camp Lejeune; (b)(6
                                                                                MIDLANT, ROICC
Camp Lejeune ; (b)(6)
                         (Group III Mgt.) (b)(6)
                                                    (PM, Group III
Management);
                            (Group III Mgt Superintendent);
                      NAVFAC MIDLANT, IPTMC
Subject: RE: PRELIMINARY CLEO TAB REPORT
All,
For continued surveillance of mechanical design issues, please keep the assigned NAVFAC ML Mechanical
Engineer copied on all mechanical design-related correspondence by including (b)(6)
                                                                                 , copied on this email
Respectfully,
          , EIT, PMP
Mechanical Acceptance Engineer
            / DSN: (b)(6)
                           / CELL: (b)(6)
                                                / FAX
----Original Message----
From: (b)(6)
                         NAVFAC MIDLANT, ROICC Camp Lejeune
Sent: Monday, May 16, 2016 1:38 PM
                                                 NAVFAC MIDLANT, CI; (b)(6)
MIDLANT, ROICC Camp (b)(6)
                                                        NAVFAC MIDLANT, ROICC Camp Lejeune;
                                                NAVFAC MIDLANT, ROICC Camp Lejeune; (b)(6)
                         (Group III Mgt.);(b)(6)
                                                   (PM, Group III Management);(b)(6)
                                                                                              (Group
III Mgt Superintendent):
Subject: RE: PRELIMINARY CLEO TAB REPORT
Hi all -
```

Sorry to jump in as I am a non-technical person. I just spoke with (b)(6)

Dragados will put in the equipment per the original design. However, this is design-bid-build. From a contracting perspective, should the equipment, if all is installed per the plans, still does not meet the required airflows, this is not the Contractor's responsibility any longer, but a design issue.

When the Contractor is not responsible for the design, we cannot hold him responsible for airflows if everything is installed per the A/E design. I believe and I are in agreement that if the CLEO is built per the plans, we will not hold up BOD for design issues. If there are any design changes, they need to be made ASAP if Dragados is intended to perform them.


Otherwise, another contract will have to follow to correct after BOD.



When you first told me about this I told you I needed to see the TAB report to see if we were in tolerance and we're not. An RFI was asked about this a while back and we stated in that RFI that HP-1 was HP-1 and HP-2 was HP-2. The airflows on the schedule match the total airflow of all the diffusers for each unit. As I told you the cooling capacity for HP-2 is higher because

HP-2 has more outside air than HP-1. If you look at the sensible load on the schedule you will see that HP-1 has a higher sensible load than HP-2.

Sincerely,



```
To: (b)(6) (b)(6) (NAVFAC)(b)(6) (NAVFAC Contract Spec) (b)(6) (NAVFAC Contract Spec) (b)(6) (Group III Mgt.) (b)(6) (Group III Mgt.) (b)(6) (Group III Mgt.) (
```

you've known for weeks that HP1 and HP2 are reversed. I told you this myself. They were reversed by my subcontractor based off of the numbers for the total cooling capacity for HPs 1&2 shown on WM602. If your position is that you want to see HP1 &HP2 installed per the plan then our request to NAVFAC is that you produce data from your calculations that this configuration will achieve what you want given HP sizes of 3.5 and 4.9. I am on my way over to NAVFAC now to discuss this. Thanks. R(b)(6)

```
(b)(6) | Deputy Project Manager & Small Business Liaison | cid:image001.png@01CCA871.8C8E7960 |

311 Parachute Tower Road | Camp Lejeune, NC 28542 |

Phone: w (b)(6) | c (b)(6) | Email: (b)(6) |

<mailto(b)(6) | >
```

Dragados USA, Inc. is An Equal Opportunity Employer

**** Confidential *****

This electronic message transmission contains information from Dragados USA Inc., that may be confidential or privileged. The information is intended to be for the use of only the individual or entity named above and not to be distributed to other companies or individuals. If you are not the intended recipient, be aware that any disclosure, copying, distribution or use of the contents of this information is strictly prohibited. If you have received this electronic transmission in error, please notify the sender by reply e-mail immediately and delete this e-mail and any attachments from your system and any copies you may have made, electronic or otherwise.

```
From: (b)(6) [mailto (b)(6) ]

Sent: Monday, May 16, 2016 11:50 AM

To (b)(6) (NAVFAC); (b)(6)
(b)(6) (NAVFAC Contract Spec); (b)(6)
(b)(6) (Group III Mgt.); (b)(6) (PM, Group III Management); (b)(6)


III Mgt Superintendent); (b)(6)


Subject: RE: PRELIMINARY CLEO TAB REPORT
```

(b)(6)

The only issues we see is HP-1 was installed as HP-2 and vice versa. This is causing the units to not meet the design airflows. Recommend installing the heat pumps as shown on the contract drawings. Also for the next TAB report please provide each heat pump airflows on high and low speed.

Sincerely,





Re-sending this email. (b)(6) is out on leave and won't return until 6Jun. I request to find out from (b)(6) (CEMS) and (b)(6) (NAVFAC Norfolk) you thoughts on the initial TAB performance results (HP-1 is at 85% of design). We will be performing TAB again once we replace dampers in the CLEO. Thanks.

I do not think that the TAB results will change too much after we install the new dampers. I am confused by the specs: are heat pumps held to +/- 5% tolerance? The specs states this is the case for groups 2 & 3. Heat pumps are in ground 1.

If the heat pumps, as installed, aren't accepted at 85% of design we will request CEMS runs their model again using the data shown on WM602 (attached) before we take additional steps. We think the 2 high-lighted numbers may be inadvertently reversed. Thanks. R/(b)

applied to TAB work this phase means "a measurement taken during TAB field acceptance testing which does not
fall within the range of plus 5 to minus 5 percent of the original measurement reported on the TAB Report for a
specific parameter."

3.3.9.1 TAB Field Acceptance Testing

During the field acceptance testing, verify, in the presence of the COTR, random selections of data (water, air quantities, air motion,) recorded in the TAB Report. Points and areas for field acceptance testing are to be selected by the COTR. Measurement and test procedures are the same as approved for TAB work for the TAB Report.

Field acceptance testing includes verification of TAB Report data recorded for the following equipment groups:

Group 1: All heat pumps and pumps.

Group 2: 25 percent of the return grilles, return registers, exhaust grilles and exhaust registers.

Group 3: 25 percent of the exhaust fans.

Further, if any data on the TAB Report for Groups 2 through 3 is found not to fall within the range of plus 5 to minus 5 percent of the TAB Report data, additional group data verification is required in the presence of the COTR. Verify TAB Report data for one additional piece of equipment in that group. Continue this additional group data verification until out-of-tolerance data ceases to be found.

Good afternoon (b) Attached is an executive summary of the CLEO TAB.

All items are within 5% of design max CFM except for HP-1. It is at 85%, or 15% shy. The design CFM for HP1 is 1100 (min) to 1450 (max). The actual reading during tab was 1231.


We will be performing TAB again once we replace dampers in the CLEO. We welcome your response to this preliminary TAB. Thanks. R/

311 Parachute Tower Road | Camp Lejeune, NC 28542 |

Dragados USA, Inc. is An Equal Opportunity Employer

**** Confidential *****

This electronic message transmission contains information from Dragados USA Inc., that may be confidential or privileged. The information is intended to be for the use of only the individual or entity named above and not to be distributed to other companies or individuals. If you are not the intended recipient, be aware that any disclosure, copying, distribution or use of the contents of this information is strictly prohibited. If you have received this electronic transmission in error, please notify the sender by reply e-mail immediately and delete this e-mail and any attachments from your system and any copies you may have made, electronic or otherwise.




Subject: RE: PRELIMINARY CLEO TAB REPORT

(b)(6)


Please provide an executive summary at the front of the report showing all items not within specification.

Sincerely,



From: (b)(6) [mailto:(b)(6)]

Sent: Monday, May 2, 2016 5:28 PM



Good afternoon . Attached is the preliminary TAB report for the CLEO building. Request your early review and comments. My team is available for a phone call if you think discussing your thoughts would help. Thanks. R/

(b)(6) | Deputy Project Manager & Small Business Liaison | |

311 Parachute Tower Road | Camp Lejeune, NC 28542 |

Phone: w (b)(6) | c (b)(6) | Email (b)(6)

Dragados USA, Inc. is An Equal Opportunity Employer

-----Original Message----From (b)(6) [mailto(b)(6)
Sent: Wednesday, April 20, 2016 1:58 PM
To (b)(6)

Subject: Fw: 224887 Field TAB Report CLEO

(b)(6)

< mailto (b)

Attached is the TAB field report. Please forward this to (b)(6) for his review and comments. We are sending this to our commissioning agent for his review and comments also (he is copied on this email).

Please let us know what (b)(6) comments are as soon as possible so we can schedule the commissioning work.

----Original Message-----

From: (b)(6)

Sent: Wednesday, April 20, 2016 11:09 AM

To: (b)(6)

Subject: FW: 224887 Field TAB Report

(b)(6)

Raleigh Division Manager / NEBB Professional

From: NAVFAC MIDLANT, CI

To: NAVFAC MIDLANT, ROICC Camp Lejeune (b) (6) NAVFAC

MIDLANT, ROICC Camp Lejeune; (b) (6)

Cc: (b)(6) (PM, Group III Management) (b)(6) (Group III Mgt Superintendent); (b)(6)

Subject: RE: CAMP LEJEUNE WILSON GATE VISITOR"S CENTER - ACOUSTICAL WALL TREATMENT

Date: Wednesday, May 25, 2016 13:50:05

(b)(6)

Are any of the following available?

Tek-wall Parable 398650 #006 Value Tek-wall Subject 399535 #003 Snowcap Tek Wall Sum 399592 #003 Blizzard

Any of those three would be acceptable.

V/r,
(b)(6) , CID
NAVFAC Mid-Atlantic
Capital Improvements, CI4B
Interior Designer
Office (b)(6)

Fax: (b)(6)

-----Original Message-----

From: (b)(6) [mailto:(b)(6)

Sent: Thursday, May 19, 2016 5:10 PM

To (b)(6) NAVFAC MIDLANT, CI;(b)(6) NAVFAC MIDLANT, ROICC

Camp Lejeune; (b)(6) NAVFAC MIDLANT, ROICC Camp Lejeune; (b)(6)

(b)(b) So(b)(6)

Cc (b)(6) (PM, Group III Management) (b)(6)

(b)(6) (Group III Mgt Superintendent); (b)(6)

Subject: [Non-DoD Source] CAMP LEJEUNE WILSON GATE VISITOR'S CENTER - ACOUSTICAL WALL

TREATMENT Importance: High

RE-SENDING: I forgot to include supporting information. Thanks. R/

Good afternoon (b)(6). The acoustic wall panel color that was submitted and approved in the submittal is no longer available. The fabric style you proposed was a Maharam fabric style and the color was TEK-WALL view 399432; 004 glacier. The manufacturer says this color is being phased out. They don't have any leftover stock. Maharam recommends the following as alternatives.

Tek-Wall 1002 001

Tek-Wall Annex 001, 002, 008

Tek-Wall Drift 004

Tek-Wall Lintel 003, 004

Tek-Wall Lintel 003, 004

Tek-Wall Measure Backed 003, 001

Tek-Wall Ramble 001

Tek-Wall Steward 001

Tek-Wall Tint 003, 002

Tek-Wall View 001, 003, 102

These can be viewed easily and clearly on their website at http://maharam.com/search?query=tek-Wall http://maharam.com/search?query=tek-Wall>

Will you please review and select an alternate color? Thanks. R. (b)(6)

| Deputy Project Manager & Small Business Liaison | cid:image001.png@01CCA871.8C8E7960 |
311 Parachute Tower Road | Camp Lejeune, NC 28542 |

| Email: (b)

Dragados USA, Inc. is An Equal Opportunity Employer

Phone: w

<mailto